

EWSW02
Location Dry
(could not be sampled)

Chemical of Interest	Conc. (mg/L)
Dissolved Copper	0.00338 J/0.00331
Total Acrolein	<0.00096/<0.00096

EWSW01

Former
Surface
Impoundment
Area

EWSW03

Chemical of Interest	Conc. (mg/L)
Dissolved Copper	0.00854

EWSW04


Chemical of Interest	Conc. (mg/L)
Dissolved Silver	0.000011 J

EXPLANATION


- Gulfco Marine Maintenance Site Boundary (approximate)
- BERA Surface Water Sample Location
- BERA Surface Water Reference Sample Location

Notes
J - Estimated Value

All Concentrations in mg/L



Approx. Scale in Feet



Source of photo: H-GAC, Texas aerial photograph, 2006.

TITLE:
**WETLAND SURFACE WATER
SAMPLE LOCATIONS**

REPORT:
FINAL BASELINE ECOLOGICAL RISK ASSESSMENT

SITE:
**GULFCO MARINE MAINTENANCE
FREEPORT, BRAZORIA COUNTY, TEXAS**

PROJECT: 41568745
DATE: MARCH, 2011

DRAWN: ZGK/NAB
CHECKED: DL

FIGURE:
7

10550 RICHMOND AVE., SUITE 155
HOUSTON, TEXAS 77042
PH: 713-914-6699
FAX: 713-914-8404